



1/5

FIG. 1





FIG. 2



2/5

FIG. 3





FIG. 4



3/5

FIG.5





FIG.6



4/5

FIG. 7







FIG. 8



5/5



No Ta redeposition –  
poor liner coverage on  
trench bottom



Ta redeposition – thick  
liner coverage on trench  
bottom

FIG. 9

FIG. 10

BEST AVAILABLE COPY